



<p>LEGEND</p> <p>ABANDONED MONITORING WELL</p> <p>MONITORING WELL</p> <p>RECOVERY WELL</p> <p>TEMPORARY WELLS</p> <p>PROPERTY LINE (APPROXIMATE)</p> <p>STORM SEWER</p> <p>SANITARY SEWER</p> <p>O/H POWER</p> <p>RESIDENTIAL HOME * DETACHED GARAGES & SHEDS NOT SHOWN</p> <p>NON-RESIDENTIAL STRUCTURE</p> <p>PRIMARY BUILDING WALLS</p> <p>(117) TCE CONCENTRATION IN ug/L</p> <p>TCE CONCENTRATION >1.2 ug/L</p> <p>TCE CONCENTRATION >5 ug/L</p> <p>TCE CONCENTRATION >9.1 ug/L</p> <p>TCE CONCENTRATION >38 ug/L</p>	<p>DRAWN BY: L. STRUM</p> <p>DATE: 9/27/99</p> <p>REVISED: 04/03/2019</p> <p>HWPA #111291-01</p> <p>DWG. NO. 111291S1</p>	<p>FIGURE 2</p> <p>TCE GROUNDWATER</p> <p>ISOCONCENTRATION MAP</p>	<p>FORMER AMPHENOL RFI/CMS</p> <p>980 HURRICANE ROAD</p> <p>FRANKLIN, INDIANA</p>	<p>IWM</p> <p>CONSULTING GROUP</p>
--	---	--	---	------------------------------------